

L Number	Hits	Search Text	DB	Time stamp
1	640	(73/1.16-1.36).ccls.	USPAT	2004/06/09 08:34
2	640	(73/1.16,1.17,1.18,1.19,1.21,1.22,1.23,1.24).ccls.	USPAT	2004/06/09 08:35
3	329	(702/87,88,100).ccls.	USPAT	2004/06/09 08:36
4	934	((73/1.16,1.17,1.18,1.19,1.21,1.22,1.23,1.25).ccls.) or ((702/87,88,100).ccls.)	USPAT	2004/06/09 08:37
5	7390	(flowmeter\$ or meter\$ or sens\$ or detect\$) near15 (adjust\$ or calibrat\$ or correct\$) near15 zero\$	USPAT	2004/06/09 10:53
6	1279	(determin\$ or measur\$ or sens\$ or detect\$ or comput\$ or test\$ or calculat\$) near12 plurality near8 zero\$	USPAT	2004/06/09 08:44
7	10	((((73/1.16,1.17,1.18,1.19,1.21,1.22,1.23,1.25).ccls.) and ((flowmeter\$ or meter\$ or sens\$ or detect\$ or comput\$ or test\$ or calculat\$) near12 plurality near8 zero\$))	USPAT	2004/06/09 08:44
10	1	6072438\$pnnear15 zero\$) and ((determin\$ or measur\$ or sens\$ or detect\$ or comput\$ or test\$ or calculat\$) near12 plurality near8 zero\$)	USPAT	2004/06/09 10:19
11	1652927	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 10:19
12	1	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 10:19
17	121	((flowmeter\$ or meter\$ or sens\$ or detect\$ or correct\$) near15 (adjust\$ or calibrat\$ or correct\$) near15 zero\$) and ((determin\$ or measur\$ or sens\$ or detect\$ or comput\$ or test\$ or calculat\$) near12 plurality near8 zero\$)	USPAT	2004/06/09 10:54
18	457	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 11:57
19	12	((flowmeter\$ or meter\$ or sens\$ or detect\$ or correct\$) near15 (adjust\$ or calibrat\$ or correct\$) near15 zero\$) and ((determin\$ or measur\$ or sens\$ or detect\$ or comput\$ or test\$ or calculat\$) near12 plurality near8 zero\$) not	USPAT	2004/06/09 11:51
20	1	6072438.pn. and (zero mass flow)	USPAT	2004/06/09 11:01
23	0	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 11:56
24	0	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 11:57
29	0	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 12:11
30	4	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 12:10
31	4	6272438.pn. and (zero mass flow)	USPAT	2004/06/09 12:11
32	0	(comput\$ or calculat\$ or determin\$) near8 zero\$ near12 plurality near8 (temperature\$ or pressure\$) near35 (flowmeter\$ or (flow near8 meter\$))	USPAT	2004/06/09 12:15

